

**47 Mollbrook Drive**

Photos from Site Inspection on 1/22/2021



A. Photos of cleared area facing Southeast with watercourse in the distance.



B. Photos of cleared area facing South with watercourse in the distance.





C. Photo of cleared area facing Southwest.



D. Photo of cleared area facing Southwest, watercourse is to the East.





E. Photo of second cleared area facing North, watercourse is to the West.