

Views of Carriage Barn at 14 Grumman Ave., Wilton, CT



Top, east side of carriage barn, viewed facing west.

Bottom, north and east sides of carriage barn, viewed facing southwest.



Top left, west wall, viewed facing northeast.

Top right, profile of inverter projecting from wall (12 inches beyond roof line).

Bottom, west wall, viewed facing east.



Top, south wall viewed to the north.

Bottom, south wall viewed to the northwest.



Location of mini-split units on interior of west wall, second floor.



Top, east wall interior (garage doors directly below on this side)
Bottom, knee walls are on north and south side interior.



Top, south-facing view of property, showing at far right, profile of west wall with inverters in the shade of wooded area near property line.

Bottom, southwest and northeast views toward rear property boundary (which is in the woods, not at the edge of grass area. Trees and understory growth provide screening of west wall.