



Photo #1: Wall at southwest property corner.

Photo Date: 8-2-23
Environmental Land Solutions, LLC

Site Photos
53 Sugar Loaf Drive, Wilton



Photo #2: Looking north along western property line.

Photo Date: 8-2-23
Environmental Land Solutions, LLC

Site Photos
53 Sugar Loaf Drive, Wilton



Photo #3: Looking north along 53 western property line near the 40/46 Sugar loaf Drive corner.



Photo #4: Looking south along property line near 40/46 Sugar Loaf Drive corner of completed portion of wall.

Photo Date: 8-2-23
Environmental Land Solutions, LLC

Site Photos
53 Sugar Loaf Drive, Wilton



Photo #5: Looking north along property line, one impacted tree from wall.

Photo Date: 8-2-23
Environmental Land Solutions, LLC

Site Photos
53 Sugar Loaf Drive, Wilton



Photo #6: Looking east from 46 Sugare Loaf Drive - misc. fill in unfinished wall to be removed.



Photo #7: Looking south along 46/53 Sugar Loaf of property line.

Photo Date: 8-2-23
Environmental Land Solutions, LLC

Site Photos
53 Sugar Loaf Drive, Wilton



Photo #8: Taken from 46 Sugar Loaf Drive, looking north along property line.



Photo #9: Soil sedimentation at 46 Sugar Loaf Drive.