SOIL & WETLAND SCIENTIST CERTIFIED PROFESSIONAL IN SOIL EROSION AND SEDIMENT CONTROL GEOLOGIST/HYDROGEOLOGIST LANDSCAPE DESIGNER



February 3, 2024


To: Michael Conklin, Director of Environmental Affairs

From: Aleksandra Moch, Environmental Consultant

Re: 0 Mountain Road – site inspection

Based on our conversation over the phone on Friday, I had inspected the site on Saturday to check the site condition after recent soil testing needed for the drainage and septic design.

I have walked the access and was able to located all of the test holes based on the soil disturbance. All of them however were located outside of the wetland buffer and away from the area of the sub-basin watershed draining towards the wetland area. The condition of the wetland crossing and the section of the access located within the wetland buffer are documented on the pictures below. The pictures were taken from the south to the north. The last picture shows the buffer area viewed from the north.



Wetland buffer viewed from the south.



SOIL & WETLAND SCIENTIST CERTIFIED PROFESSIONAL IN SOIL EROSION AND SEDIMENT CONTROL GEOLOGIST/HYDROGEOLOGIST LANDSCAPE DESIGNER









SOIL & WETLAND SCIENTIST
CERTIFIED PROFESSIONAL IN SOIL EROSION
AND SEDIMENT CONTROL
GEOLOGIST/HYDROGEOLOGIST
LANDSCAPE DESIGNER









SOIL & WETLAND SCIENTIST CERTIFIED PROFESSIONAL IN SOIL EROSION AND SEDIMENT CONTROL GEOLOGIST/HYDROGEOLOGIST LANDSCAPE DESIGNER





View of the wetland buffer area from the north

Based on my site inspection, there was no disturbance noted with the wetland or wetland buffer area. The site was in compliance.

As of the disturbed areas located outside of the wetland and wetland buffer area, they are going to be smoothed and covered with leaf mulch to keep the area stable. Unusually wet condition caused by the prolonged precipitation make the site challenging for the movement of heavy equipment in some areas.

I will report back next week when the other areas are mulched.

Please let me know if you have any questions 203 550 9373.

