

# Annex & Town Hall Ceilings



#### Annex Back Door




#### Annex Bathrooms



#### Annex Old Entrance




Annex Women's Bathroom



Town Hall Hallway Ceiling



# Town Hall & Annex Ceilings



# Town Hall Ceilings



Wilton Town Hall Finance Office Ceiling



#### Town Clerk Area



# Town Clerk Ceilings



# Town Clerk Hallway



Town Clerk Offices Entrance



#### **Town Clerk Offices**



### Town Clerk Window Area



### Town Hall Other Columns




# Town Hall Replaced Column



#### Town Hall Front



### Town Hall Front Steps




#### Town Hall Front



Ambler Farm – Yellow House






Gilbert & Bennett School Basement with pipes bust damage

### Gilbert & Bennett School Bathroom




Gilbert & Bennett School Front door handle



Gilbert & Bennett School Front Door



Gilbert & Bennett School Roof Leak



Gilbert & Bennett School Roof

