

## 141 DANBURY ROAD SOILS TESTING



Map showing location of testing on 9/20/2021. TP-4 was located at the black X to the right of the handwritten TP-4. TP-3 was also dug yesterday. TP-5 was being dug around 12:15 pm on 9/20.



Location of TP-4 in parking area.





*TP-4 percolation test. Top of perc hole is 3' below pavement grade. Water level in hole did not percolate into the soil during the 30 minute +/- duration it was observed.*



*TP-4 percolation test. Top of perc hole is 4' below pavement grade. Water level in hole again did not percolate into the soil during the 30 minute +/- duration it was observed.*





*TP-5 percolation test. Top of perc hole is 4' below pavement grade. Water level in hole readily percolated into the ground during the test.*



*TP-5 percolation test. Top of perc hole is 4' below pavement grade. Water level in hole readily percolated into the ground during the test.*