

## Memorandum

June 30, 2020

To: Peter Romano

From: Chris Allan  
Registered Soil Scientist,  
Professional Wetland Scientist

Subject: 141 Danbury Road  
Wilton, CT

---

I inspected the proposed plant restoration area between the eastern bank of the Norwalk River and the paved parking area at 141 Danbury Road on June 24, 2020. Based on my evaluation of the soils in this area, it was determined that the entire restoration area consists of historic fill associated with construction of the existing paved parking lot. A small area of well-drained alluvial soil is located at the southern limit of the proposed restoration area. These alluvial soils form a portion of the river bank west of the proposed restoration area and are considered a wetland soil type. The approximate limit of the alluvial soils is shown on the attached figure. No other wetland soil types were identified east of the river bank.