

230 Ridgefield Road

Photos from Site Inspection 3/16/21



A. Photo of cleared area on Southern portion of property, along river.



B. Photo of cleared area on Southern portion of property, along river.



C. Photo of two (2) removed trees on Southern portion of property.



D. Photo of cleared area on Southern portion of property, along river.



E. Photo of cleared area on Eastern portion of property, along stream.



F. Photo of culvert created for roadway to cross stream. Eastern portion of property.



G. Photo of culvert and newly created roadway.



H. Photo of roadway along cleared wetland, Northern portion of property.



I. Photo of wetland area cleared of all understory vegetation, Northern portion of property.



J. Photo of wetland area cleared of all understory vegetation, Northern portion of property.



K. Photo of roadway created through cleared wetland, Northern portion of property.

L. Panoramic photo of cleared area to illustrate the extent of work.
(On next page)





M. Photo of filled in pool and wood piles, Northern portion of property.



N. Photo of wood piles, Northern portion of property.